


# WORKFLOW GUIDELINES


## MODELING

- 1) Check for free surfaces and merged parts
  - Import only solids
  - Do not merge parts
    - Part definition becomes complex
    - Solver works harder
    - Solution accuracy and performance can deteriorate
  
- 2) Check for solids with curvature
  - If the faceting of those solids is coarse, bring in finer resolution of those parts
  - Do not import the entire assembly with finer resolution, it will slow down the solution considerably
  
- 3) Check for geometry errors
  
- 4) Make sure parts are classified correctly (bolts, nuts, springs etc.)


RMB Assembly > Show



Settings > Geometry  
Import Settings




Assembly > check  
geometry error



## 5) Create welded connections, if applicable

- Connections in SimSolid should represent connections of the parts in the field

## Connections &gt; Seam/Spot Welds



## 6) Create auto-connections using normal resolution

- Use small tolerance
- Identify and connect any free parts
- Make sure the structure is not over-constrained
- Delete any redundant connections


## 7) Identify connections with small # of points

- Edit those connections to have higher resolution


## 8) Review parts with small relative volume

- Verify that they have enough connection points


## Connections &gt; Find/Show disconnected parts



## Connections &gt; Review regular connections




## Assembly &gt; Review parts



## SOLUTION SETTINGS

- 1) Run linear static analysis
  - Identify local deformations, thin curved solids, parts of interest for stresses
  
- 2) Create local groups for identified parts and organize them based on part scale
  - **Group parts with similar scale**
  - Apply relevant solution settings (refinement level, adapt to features, adapt to thin solids)
  - Adapt to features: Groups where accurate stresses are required
  - Adapt to thin solids: Groups where there are thin **curved** solids
  - High refinement level: Global-local analysis and groups with local deformations
  
- 3) Increase contact resolution (if applicable)
  - Increase resolution of contact interfaces where stresses are important/high
  - Do not always use higher resolution on the entire assembly, it will negatively affect the performance of the solution
  
- 4) Increase the number of adaptive solutions to 4-5-6 until convergence is achieved
  - Do not go beyond 6 adaptive passes
  - Higher number of passes cause chatter around contact connections
  
- 5) Perform nonlinear analysis only after achieving accurate linear solution

### Project tree > Project solution settings



### Add/Edit connection

